

Trouble shooting for error 08

Suitable for SAKO inverter: SUNSEE/SUNON/SUNON PLUS/SUNPOLO

Error code 08: Bus voltage is too high

Trouble shooting:

Step 1. Disconnect the load, grid input and solar input. Just connect battery and turn on the inverter. If still problem, go to step 2.

Step 2. Check if the battery voltage and solar input voltage is too high, and if they are connected correctly. If their input voltage is in the proper range and OK, go to step 3.

Step 3. Disconnect all power source, and open the top cover, take out the main board, place the main board on the insulated tables. Test the DC to AC drive circuit with multimeter (See as below picture), and replace the damaged components.

